

QUALIFIED ELECTRONIC TECHNICIANS SHOULD ONLY PERFORM THIS ENHANCEMENT. PEAVEY ELECTRONICS WILL NOT BE RESPONSIBLE FOR EQUIPMENT DAMAGED AS A RESULT OF IMPROPER INSTALLATION OF THE PARTS. SHOULD YOU HAVE QUESTIONS REGARDING THIS INSTALLATION, PLEASE DO NOT HESITATE TO CONTACT OUR REPAIR ASSISTANCE DEPARTMENT AT THE FACTORY BY PHONING (601) 483-5365.

PEAVEY SESSION 500 TONE ENHANCEMENT KIT

<u>FROM</u>	<u>TO</u>	DESIGNATION	PEAVEY#
.1uf	2.2uf/50v	C1	70320010
2.2uf	22uf/25v	C6	70320012
.0068uf	.0047uf/100v	C26&C27	70330069
220K res.	1 Meg	R3	70240039
4558	OPA2604	U2,U6,U7,U20	c57000092
5532	OPA2604	U1,U11	c57000092

IC LOCATIONS U4,U5,U13,U14,U15,U16,U17,U18 AND U19 DO NOT HAVE TO BE REPLACED. FACTORY IC'S PERFORM WELL WITHOUT THE REPLACEMENT OF THESE COMPONENTS.

REASSEMBLE AMP IN REVERSE ORDER AND TEST.

NOTE; MAKE SURE THAT YOU INSERT THE IC CHIPS CORRECTLY AND SEAT THEM PROPERLY IN THEIR SOCKETS. THERE IS A NOTCH AT THE END OF THE SOCKET AND AT THE END OF THE IC CHIP THAT SHOULD BE MATCHED WHEN INSTALLING.

6/17/2003